

LASPOZAS PHOTOGRAPH LOG
OCTOBER 1998 INSPECTION DRAFT FOR COMMENT
8/5/98

ENTRY NUMBER	DATE	NEGATIVE ROLL NUMBER	SHOT NUMBER	STRUCTURE		PHOTO LOOKING DIR (N,E,S,W)	ELEVATION FEET	INSIDE OUTSIDE	DESCRIPTION OF STRUCTURE
				NAME	NUMBER				
1		#7	785	EDWARD'S HOUSE		E NW		0	MAJOR CRACK
2			786	WALL	1ST FLR.	SOUTH.W		0	EDWARD'S HOUSE
3			787-88						CRACK support of concrete
4			789			SW		0	South west corner
5			790	MAIN SUPPORT		SOUTH		0	MAJOR BEAM (VERTICAL)
6			791	RED SPINAL	STAIRS E.H.			0	VOIDS
7			791	WALK WAY WALL	TO THE DEER GATE				EXPOSED STEEL
8			792						
9			793	SOUTH WEST COL. OF	EDWARD HOUSE		SW		TYPICAL CRACK AND THICK COAT OF WT. CEMENT
10			794	EXPOSED STEEL	MISSING PARTS		SW		STRUCTURE ARC

794 EXPOSED STEEL & MISSING PARTS

795 WEST SIDE E. HOUSE NORTH

796 LOOKING S.E OF ~~NORTH~~ EAST & E

WEST CORNER OF THE HOUSE

797 MAJOR STRUCTURAL FAILURE SE SECOND FLOOR E.H.

798 VOID, EXPOSED STEEL SW SECOND SET OF STAIRS AT E.H.

799 THE DEER'S HOUSE OR CAGE SW MAJOR CRACK at the TOP of

800 COLUMN - WEST SIDE OF ROOF - A asphalt roof deteriorating WEST THE CAP is missing

MISCELLANEOUS COMMENTS

801 -	DETAIL OF ASPHALT COVERING EAST CORNER OF ROOF.	WE -	10/16/98
802 -	AG		
803 -	MAJOR FAILURE AT THE PATH GOING TO OCELOTE'S HOUSE	NORTH	10/16/98
804	OCELOTE'S HOUSE The Bamboo House col East side	NORTH	10/16/98
805	The same column #2 major column #5		
806-808 Roll #8	Bamboo column major spalling -		
809 -	Same col #5 Spalling, cracking exposed steel rebar	Gate col. N.E. - of Ocelote House -	
810 -	EXAMPLE of Fungus #2 on 2 ext columns Ocelote house -		
810 -	Column falling down North side of Flamingo's House -		

811

EAST SIDE OF DE GATE
OF THE NORTH SIDE -
CRACK, SPALL, EXPOSED STL.

NE

10/16/98

812

FLEUR OF LYS - BRIDGE
EAST SIDE
SPALLING - FUNGUS - DECOLORATION

SOUTH -

813-814

FLEUR OF LYS
WEST SIDE

EAST SIDE

10/16/98

815 -
816

CRACK IN THE BASE OF CD. Major crack
gate north of Fleur of the Lys.
Est.

817

Base of Column Looking
East - NORTH OF THE
FLEUR OF THE LYS BRIDGE
FUNGUS #3 fleur of the Lys
BRIDGE

EAST

818-819

WEST WALL SOUTH OF
THE EDUARDO PLAZA

820 -

HOUSE OF MOLD'S
SW CORNER FOUNDATION FAILURE

SE

821-822-823

W. FOUNDATION OF THE HOUSE OF MOLD

N.

Roll #

3

~~SHOOT#~~

DESCRIPTION

VIEW .

DATE

824-826

WALK WAY OF THE
WEST SIDE HOUSE OF

NE

10/16/98

827

MOLDS .
LARGE VERTICAL CRACK
WEST SIDE OF THE HOUSE
OF MOLD

828

BUTTRESSES - LEGS COVER
WITH GREEN MOSS

829-830-831

MAJOR FAILURE AT THE BASE
OF HOUSE OF MOLDS -

10/16/98

832 -

THE SECOND FLOOR . OF PARROT
HOUSE COL #3 OF 11

NW .

10/16/98

833 -

Roll # ?

953 - 957 Oct. 17

for plaster
concrete

plaster
spalling off 2nd Floor
mid 60's SW corner

El Castillo

③

El Castillo

NE

108

2nd Floor

954

corners

w/ plaster

955

56

57

58

plaster patch

on E side